

MAHARASHTRA STATE ELECTRICITY TRANSMISSION CO. LTD.

Name of Office

: Executive Engineer, EHV O&M Division, Latur.

Office Address

: 132 kV Latur(MIDC) S/s Premises, Near Kirti Gold

Mill, MIDC Road, Latur-413512

Contact No.

: 02382-222208 (O), 8554994957 / 9607972092

Email ID

: eelaturdn@gmail.com, ee2220@mahatransco.in.

Ref. No.: EE/EHV/O&M/LTR/TS/ WU U 8 2 1 =

Date: - 2 7 SEP 2021

E-Enquiry

Sub :- E-Enquiry for Work of Repair/Reconditioning of 11 kV & 33 kV CT for EHV S/s under EHV O&M Dn, Latur

Dear Sirs,

Sealed and super scribed quotations are invited for the work as specification given below. The quotation giving full particulars should reach this office on or before. 29.10.2021, up to 15.00 Hrs positively. The Taxation liability should show separately. Rights of cancellation/modification of E-Enquiry at any stage, is reserved at this office.

Schedule 'A'

Sr No	Particulars	Unit	Qty	Unit Rate (Excl. GST)	Unit Rate (Incl. GST)	Amount in Rs. (Incl. Taxes)
A	Repair of failed CT and S/s type Out Door, Oil filled type. The Job Involves Dismantling, Vacuum and evening Treatment, Replacement of Insulation material, Provide Hardware, Terminal bushing, Gasket etc. Painting, Tank welding if required, Replacement of complete coil of failed CT Reassembling and Testing etc.					
1	11 kV CT, 2Core Ratio 200/1-1A	No.	1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-	
2	11 kV CT, 2Core Ratio 400-200-100/5-5A	No.	1			
3	11 kV CT, 3Core Ratio 1600-800/1-1-1A	No.	1			
4	11 kV CT 3 Core Ratio 400-200/5-5-5A	No.	5			
5	33 kV CT 3 Core Ratio 400-200/1-1-1A	No.	1			
6	33 kV CT 3 Core Ratio 800-400/1-1-1A	No.	3			
7	33 kV CT 4 Core Ratio 1600-800/1-1-1-1A	No.	2			
	Total (Including all Taxes)					

Estimated amount for the above work: Rs. 2,64,615 (Including all Taxes & Cess)

Note:- 1. Rate of GST shall be mentioned by Bidder on their Offer with SAC Code.

2. No Conditional bid shall be Accepted.

4. Xerox signed copies of below mentioned documents should be attached along with quotation.

a) PAN Card. b) GST registration Certificate c) Bombay Shop Act License

d) Experience certificate of same work, issued by not below the rank of Executive Engineer

Executive Engineer,
EHV O&M Division Latur