# Atharashtra State Electricity Transmission Co. Ltd.

#### **Tender for Operations and maintenance**

#### Information

24010
RFx
FOR ER B/D & OTG WORK AT 400KV SS W2
AL MAINTENANCE CONTRACT (AMC) FOR EMERGENCY BREAKDOWN & & OTHER OUTAGE ORIENTED WORK AT
2022
₹
000.00₹
).00 ₹
2022 11:00:00
2022 12:00:00
54993600 DYEE-8554993202

#### **Additional Requested Information:**

a)#Average Annual financial turnover during the last 03 years, ending 31st March of the previous financial year, should be at least 40 % of the estimated cost. Submit ONLY turnover certificate of C.A. (essential)

b)#Experience certificates of having done the "Annual Maintenance Contract (AMC) for Emergency breakdown work & Other Outage oriented work at 400KV Sub-Station" amounting to 60% of the estimated cost in maximum 3 orders during last 07 years as per SN (b)

c)#Proof of Goods & Service Tax Registration (GSTIN Registration).

d)#Copy of PAN card.

e)#Proof of Registration of Firm under Bombay shop & Establishment Act.

f)#Copy of SSI/NSIC Certificate with Memorandum (if applicable). The Registration Certificate as submitted by Micro and Small Enterprises should be VALID on the date of submission of bid and the validity of the same should be certified by the Chartered Ac

g)#Income Tax Returns of last any 03 years.

h)#Undertaking of contractor as per Annexure G on agency letter head should be submitted.

i)#Valid insurance of Labour / ESIC if applicable.

j)#Valid Electrical License Certificate.

#### Attachments:

#### • TENDER DETAIL - E-TENDER

### MAHARASHTRA STATE ELECTRICITY TRANSMISSION CO. LTD.

# Tender for Operations and maintenance



#### Information

RFx number: 7000024010 Version: 1

### **RFx Details:**

#### ( \*Amount in ₹)

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1	Outline	998736	AMC FOR OUTAGE ORIENTED WORK R FOR S/S	1.000 AU		594989.78
1.AA	Service 50015703	998736	ER_Erection of 220kV CB Erection of Circuit breaker on casted foundation with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 Set	37428.48	37428.48
1.AB	Service 50015704	998736	ER_Erection of 400kV CB Erection of Circuit breaker on casted foundation with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 Set	53036.29	53036.29

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.AC	Service 50000172	998736	Erection of 220kV CB Erection of Circuit breaker with required modification of existing foundation as per drawings with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 EA	46786.49	46786.49
1.AD	Service 50000173	998736	Erection of 420kV CB Erection of Circuit breaker with required modification of existing foundation as per drawings with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 EA	66296.26	66296.26
1.AE	Service 50015709	998736	ER_Dismantling 220kV CB Dismantling of Circuit Breaker with removal of SF6 / Oil and removal of pole, mechanism, wiring and cabling and piping, removal of support structure etc. complete for#	1.000 Set	29942.78	29942.78
1.AF	Service 50015720	998736	ER_Dismantling 400kV CB Dismantling of Circuit Breaker with removal of SF6 / Oil and removal of pole, mechanism, wiring and cabling and piping, removal of support structure etc. complete for#	1.000 Set	42429.27	42429.27

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.AG	Service 50015722	998736	ER_Erection of 220kV CT/PT Erection of Current Transformer on provided support structure WITH NECESSARY MODIFICATION with connecting the terminal connectors and jumpers on both sides with required connection with available cables to the terminal box for#	1.000 EA	4491.89	4491.89
1.AH	Service 50015723	998736	ER_Erection of 400kV CT/PT Erection of Current Transformer on provided support structure WITH NECESSARY MODIFICATION with connecting the terminal connectors and jumpers on both sides with required connection with available cables to the terminal box for#	1.000 EA	10254.25	10254.25
1.AJ	Service 50015725	998736	ER_Dismantling 220kV CT/PT Dismantling of Current transformer from support structure with removal of terminal connectors and jumpers and cabling connection from the terminal box for#	1.000 EA	3593.28	3593.28
1.AK	Service 50015726	998736	ER_Dismantling 400kV CT/PT Dismantling of Current transformer from support structure with removal of terminal connectors and jumpers and cabling connection from the terminal box for#	1.000 EA	8204.35	8204.35
1.AL	Service 50015727	998736	ER_Dismantling 132kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	2395.52	2395.52
1.AM	Service 50015728	998736	ER_Dismantling 198kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	3593.28	3593.28

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.AN	Service 50015729	998736	ER_Dismantling 390kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	4812.49	4812.49
1.AP	Service 50015730	998736	ER_Erection of 132kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	2993.80	2993.80
1.AQ	Service 50015731	998736	ER_Erection of 198kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	4491.89	4491.89
1.AR	Service 50015732	998736	ER_Erection of 398kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	6015.01	6015.01
1.AS	Service 50015749	998736	ER_Dismantling 220kV Susp. WT wt SI Dismantling of WT (PEDSTAL TYPE) with support structure removal of jumpers at both the ends, removal of support insulators etc. For#	1.000 EA	5389.32	5389.32
1.AT	Service 50015750	998736	ER_Dismantling 400kV Susp. WT wt SI Dismantling of WT (PEDSTAL TYPE) with support structure removal of jumpers at both the ends, removal of support insulators etc. For#	1.000 EA	11409.10	11409.10
1.AU	Service 50015752	998736	ER_Dismantling 220kV Susp. WT w/o SI Dismantling of WT only PEDSTAL TYPE without support structure with removal of jumpers at both the ends etc. For#	1.000 EA	3773.24	3773.24

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.AV	Service 50015753	998736	ER_Dismantling 400kV Susp. WT w/o SI Dismantling of WT only PEDSTAL TYPE without support structure with removal of jumpers at both the ends etc. For#	1.000 EA	9336.56	9336.56
1.AW	Service 50015755	998736	ER_Erection of 220kV WT wt Insulator Erection of WT PEDSTAL TYPE with support insulators, leveling, erection of WT and connecting the Jumpers at both the ends with terminal clamps provided for#	1.000 EA	5988.80	5988.80
1.AX	Service 50015756	998736	ER_Erection of 400kV Susp. WT wt SI Erection of WT PEDSTAL TYPE with support insulators, leveling, erection of WT and connecting the Jumpers at both the ends with terminal clamps provided for#	1.000 EA	12677.18	12677.18
1.AY	Service 50015758	998736	ER_Erection of 220kV WT w/o Insulator Erection of WT only PEDSTAL TYPE without support insulators, connecting the Jumpers at both the ends with terminal clamps. For#	1.000 EA	4191.56	4191.56
1.AZ	Service 50015759	998736	ER_Erection of 400kV Susp. WT w/o SI Erection of WT only PEDSTAL TYPE without support insulators, connecting the Jumpers at both the ends with terminal clamps. For#	1.000 EA	10373.43	10373.43
1.BA	Service 50019027	998736	ER_Dismantling 400kV CVT Dismantling of 420kV CVT from support structure with removal of cabling / termination from MB and stacking the same at required place as directed#	1.000 EA	10502.14	10502.14
1.BB	Service 50019026	998736	ER_Erection of 400kV CVT Erection of 420kV CVT on provided support structure with jumper connection with suitable terminal clamp provided with connecting the required cables from MB and termination complete#	1.000 EA	13127.68	13127.68
1.BC	Service 50015760	998736	ER_Repl. 22-220kV Single Ten. String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	19566.97	19566.97

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.BD	Service 50015762	998736	ER_Repl. Twin Ten. Insulator String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	26089.69	26089.69
1.BE	Service 50015763	998736	ER_Repl. Qaudraple Ten. String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	45655.47	45655.47
1.BF	Service 50015764	998736	ER_Repl. 22-220kV Single Susp. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	4097.41	4097.41
1.BG	Service 50015765	998736	ER_Repl. 22-220kV Twin Susp.Insu. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	5336.88	5336.88
1.BH	Service 50015766	998736	ER_Repl. Qaudraple Susp. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	8004.13	8004.13
1.BJ	Service 50015808	998736	ER_Dismantling 220kV BPI Dismantling of BPI from the support structure with removal of jumper and terminal clamp complete for#	1.000 EA	1437.31	1437.31
1.BK	Service 50015809	998736	ER_Dismantling 400kV BPI Dismantling of BPI from the support structure with removal of jumper and terminal clamp complete for#	1.000 EA	1842.52	1842.52
1.BL	Service 50015811	998736	ER_Erection of 220kV BPI Erection of BPI in stacks on provided support structure with leveling with fixing of terminal clamp with connecting the jumper for#	1.000 EA	1796.04	1796.04

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.BM	Service 50015812	998736	ER_Erection of 400kV BPI Erection of BPI in stacks on provided support structure with leveling with fixing of terminal clamp with connecting the jumper for#	1.000 EA	2303.75	2303.75
1.BN	Service 50015814	998736	Dismantling 220kV Couplg Cap. (ER/BD) Dismantling of CC from the support structure with removal of jumper and terminal clamps, removal of earthing complete for#	1.000 EA	3593.28	3593.28
1.BP	Service 50018538	998736	ER_Erection of 220kV Coupling Capacitor Erection of CC on provided support structure with connecting the terminal clamp and jumper connection with fixing of LMU unit with connection of HF cable, with connection of earthing complete for#		4491.89	4491.89
1.BQ	Service 50015816	998736	ER_Repl. Jumper Connection/Single Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	605.43	605.43
1.BR	Service 50015817	998736	ER_Repl. Jumper Connection/Twin Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	1210.87	1210.87
1.BS	Service 50015818	998736	ER_Repl. Jumper Connection/Quad Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	2422.93	2422.93
1.BT	Service 50015819	998736	ER_Repl. 22-220kV Jumper Conn./1Main Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	741.30	741.30

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.BU	Service 50015820	998736	ER_Repl. 22-220kV Jumper Conn./2Main Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	1333.62	1333.62
1.BV	Service 50015821	998736	ER_Repl. Jumper Connection/Quad Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	2668.44	2668.44
1.BW	Service 50015822	998736	ER_Repl. 22-220kV Jumper Conn./1Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	889.08	889.08
1.BX	Service 50015823	998736	ER_Repl. 22-220kV Jumper Conn./2Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	1482.60	1482.60
1.BY	Service 50015824	998736	ER_Repl. Jumper Connection/Quad Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	2965.20	2965.20
1.BZ	Service 50015825	998736	ER_Repl. Single Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	605.43	605.43
1.CA	Service 50015826	998736	ER_Repl. Twin Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	1210.87	1210.87

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.CB	Service 50015827	998736	ER_Repl. Quad Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	2422.93	2422.93
1.CC	Service 50010134	998736	Dismantling&Erection of IPS tube Replacement of IPS tube from the equipment terminals in 400kV switchyard with removal of terminal connectors at both ends and its re-erection with provided terminal connectors#	1.000 EA	458.84	458.84
1.CD	Service 50008567	998736	Fixing 4" Al IPS Tube Fixing of IPS tube on Post Insulators ( 400kV or 33kV - tertiary ) with provided clamp as directed#	1.000 EA	255.05	255.05
1.CE	Service 50014788	998736	Fabr.&Cutting for 4" IPS Tube Fabrication of IPS Jointing Sleeves as per drawings#	1.000 EA	1779.36	1779.36
1.CF	Service 50006570	998736	Argon Welding of IPS Tube Per Joint Welding of IPS tubes joints as per site requirement with argon welding as directed to make the joint smooth#	1.000 EA	5929.21	5929.21
1.CG	Service 50018234	998736	Dismantling IPS Tube wt Str Dismantling of 4" IPS tube including supply of all labour T&P etc. complete.#	1.000 RMT	203.80	203.80
1.CH	Service 50015697	998736	ER_Crimping of Single T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	593.52	593.52
1.CJ	Service 50015696	998736	ER_Crimping of Twin T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	1185.84	1185.84
1.CK	Service 50015695	998736	ER_Crimping of Quad T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	1779.36	1779.36

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.CL	Service 50015691	998736	ER_Crimping of 132/220kV Jumper Cone Crimping works FOR CONDUCTOR with suitable size capacity crimping machine with suitable size DIES for JUMPER CONE at ground#	1.000 EA	474.34	474.34
1.CM	Service 50015693	998736	ER_Crimping of 400kV Jumper Cone Crimping works FOR CONDUCTOR with suitable size capacity crimping machine with suitable size DIES for JUMPER CONE at ground#	1.000 EA	948.67	948.67
1.CN	Service 50015692	998736	ER_Crimping of 132/220kV Repair Sleeves Crimping works ON CONDUCTOR FOR REPAIR SLEEVES ( Overhead ) with suitable size capacity crimping machine with suitable size DIES#	1.000 EA	2371.68	2371.68
1.CP	Service 50017771	998736	ER_Laying of 4Cx10mm <sup>2</sup> Cable	1.000 RMT	20.26	20.26
1.CQ	Service 50017768	998736	ER_Laying of 3 <sup>1</sup> / <sub>2</sub> Cx70mm <sup>2</sup> Cable	1.000 RMT	66.74	66.74
1.CR	Service 50017052	998736	Laying,Dress&Clamping 3.5Cx35mm <sup>2</sup> Cable	1.000 RMT	66.74	66.74
1.CS	Service 50009523	998736	Laying&Term. 7Cx2.5mm <sup>2</sup> Cu Cable	1.000 RMT	22.64	22.64
1.CT	Service 50007561	998736	Laying,Dress&Clamping 10Cx2.5mm <sup>2</sup> Cable	1.000 RMT	29.79	29.79
1.CU	Service 50017759	998736	ER_Laying of 14Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	29.79	29.79
1.CV	Service 50005249	998736	Laying of 19Cx2.5mm <sup>2</sup> Cu Flex. Cable	1.000 RMT	29.79	29.79
1.CW	Service 50004899	998736	Laying&Term. 2Cx2.5mm <sup>2</sup> Cu Cable	1.000 RMT	14.30	14.30
1.CX	Service 50004921	998736	Laying of 4Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	22.64	22.64
1.CY	Service 50015522	998736	Laying of 3 <sup>1</sup> / <sub>2</sub> Cx120mm <sup>2</sup> Al Ar Cable	1.000 RMT	75.08	75.08
1.CZ	Service 50017674	998736	ER_Dismantling 4Cx10mm <sup>2</sup> Cable	1.000 RMT	16.69	16.69
1.DA	Service 50017672	998736	ER_Dismantling 3 <sup>1</sup> / <sub>2</sub> Cx70mm <sup>2</sup> Cable	1.000 RMT	53.63	53.63
1.DB	Service 50017671	998736	Dismantling 3.5Cx35mm <sup>2</sup> Cable -Otg	1.000 RMT	53.63	53.63
1.DC	Service 50016768	998736	Dismantling 7Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	17.87	17.87
1.DD	Service 50016752	998736	Dismantling 10Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	23.83	23.83

# Tender for Operations and maintenance

#### Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
1.DE	Service 50016769	998736	Dismantling 14Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	23.83	23.83
1.DF	Service 50016770	998736	Dismantling 19Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	23.83	23.83
1.DG	Service 50016750	998736	Dismantling 2Cx2.5mm <sup>2</sup> Cu Ar Cable	1.000 RMT	11.91	11.91
1.DH	Service 50017666	998736	ER_Dismantling 3 <sup>1</sup> / <sub>2</sub> Cx120mm <sup>2</sup> Cable	1.000 RMT	60.78	60.78
1.DJ	Service 50017822	998736	ER_Termination 4Cx10mm <sup>2</sup> Cable Both End	1.000 EA	303.91	303.91
1.DK	Service 50017820	998736	ER_Termination 3 <sup>1</sup> / <sub>2</sub> x70mm <sup>2</sup> Cable Both End	1.000 EA	1350.31	1350.31
1.DL	Service 50017818	998736	ER_Termination 3 <sup>1</sup> / <sub>2</sub> x35mm <sup>2</sup> Cable Both End	1.000 EA	1350.31	1350.31
1.DM	Service 50017832	998736	ER_Termination 7Cx2.5mm <sup>2</sup> Cable Both End	1.000 EA	338.47	338.47
1.DN	Service 50017801	998736	ER_Termination 10Cx2.5mm <sup>2</sup> Cable	1.000 EA	438.58	438.58
1.DP	Service 50017805	998736	ER_Termination 14Cx2.5mm <sup>2</sup> Cable	1.000 EA	438.58	438.58
1.DQ	Service 50017807	998736	ER_Termination 19Cx2.5mm <sup>2</sup> Cable	1.000 EA	438.58	438.58
1.DR	Service 50017813	998736	Termination 2Cx2.5 Cable Both End -Otg	1.000 EA	237.17	237.17
1.DS	Service 50017826	998736	ER_Termination 4Cx2.5mm <sup>2</sup> Cable Both End	1.000 EA	303.91	303.91
1.DT	Service 50017814	998736	ER_Termination 3 <sup>1</sup> / <sub>2</sub> x120mm <sup>2</sup> Cable Both End	1.000 EA	1755.22	1755.22
1.DU	Service 50003606	998736	Hiring of Crane (Day)	1.000 DAY	10102.39	10102.39
1.DV	Service 50017809	998736	ER_Termination 2Cx10mm <sup>2</sup> Cable Both End	1.000 EA	237.17	237.17
1.DW	Service 50015694	998736	ER_Crimping of 400kV Repair Sleeves	1.000 EA	4743.36	4743.36
2	Outline	998736	AMC FOR EMERGENCY ORIENTED WORK R S/S	1.000 AU		699286.27

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.AA	Service 50015703	998736	ER_Erection of 220kV CB Erection of Circuit breaker on casted foundation with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 Set	44915.37	44915.37
2.AB	Service 50015704	998736	ER_Erection of 400kV CB Erection of Circuit breaker on casted foundation with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 Set	63643.31	63643.31
2.AC	Service 50000172	998736	Erection of 220kV CB Erection of Circuit breaker with required modification of existing foundation as per drawings with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 EA	56143.31	56143.31

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.AD	Service 50000173	998736	Erection of 420kV CB Erection of Circuit breaker with required modification of existing foundation as per drawings with erection of support structure its leveling, mechanism, pole, required piping cabling and termination up to MB, earthing of CB poles and structures , MB etc. with filling of SF6 if required to specified pressure, fixing of related accessories etc. complete as directed by the Mfg. manual and assisting testing and attending the problems if any up to commissioning for (SF6 shall be supplied by MSETCL.)#	1.000 EA	79555.03	79555.03
2.AE	Service 50015709	998736	ER_Dismantling 220kV CB Dismantling of Circuit Breaker with removal of SF6 / Oil and removal of pole, mechanism, wiring and cabling and piping, removal of support structure etc. complete for#	1.000 Set	35931.58	35931.58
2.AF	Service 50015720	998736	ER_Dismantling 400kV CB Dismantling of Circuit Breaker with removal of SF6 / Oil and removal of pole, mechanism, wiring and cabling and piping, removal of support structure etc. complete for#	1.000 Set	50914.89	50914.89
2.AG	Service 50015722	998736	ER_Erection of 220kV CT/PT Erection of Current Transformer on provided support structure WITH NECESSARY MODIFICATION with connecting the terminal connectors and jumpers on both sides with required connection with available cables to the terminal box for#	1.000 EA	5389.32	5389.32
2.AH	Service 50015723	998736	ER_Erection of 400kV CT/PT Erection of Current Transformer on provided support structure WITH NECESSARY MODIFICATION with connecting the terminal connectors and jumpers on both sides with required connection with available cables to the terminal box for#	1.000 EA	12305.34	12305.34

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.AJ	Service 50015725	998736	ER_Dismantling 220kV CT/PT Dismantling of Current transformer from support structure with removal of terminal connectors and jumpers and cabling connection from the terminal box for#	1.000 EA	4311.93	4311.93
2.AK	Service 50015726	998736	ER_Dismantling 400kV CT/PT Dismantling of Current transformer from support structure with removal of terminal connectors and jumpers and cabling connection from the terminal box for#	1.000 EA	9844.27	9844.27
2.AL	Service 50015727	998736	ER_Dismantling 132kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	2874.62	2874.62
2.AM	Service 50015728	998736	ER_Dismantling 198kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	4311.93	4311.93
2.AN	Service 50015729	998736	ER_Dismantling 390kV LA Dismantling of LA from the support structure with removal of jumper from terminal connector, and stacks with stacking with removal of earthing connection and LA counter etc. complete for#	1.000 EA	5774.27	5774.27
2.AP	Service 50015730	998736	ER_Erection of 132kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	3593.28	3593.28

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.AQ	Service 50015731	998736	ER_Erection of 198kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	5389.32	5389.32
2.AR	Service 50015732	998736	ER_Erection of 398kV LA Erection of LA on provided support structure with minor modification with stacks, insulator base, with leveling, connecting terminal connector and jumper connection with connecting the counter, with earthing connection etc. complete for#	1.000 EA	7218.73	7218.73
2.AS	Service 50015749	998736	ER_Dismantling 220kV Susp. WT wt SI Dismantling of WT (PEDSTAL TYPE) with support structure removal of jumpers at both the ends, removal of support insulators etc. For#	1.000 EA	6467.90	6467.90
2.AT	Service 50015750	998736	ER_Dismantling 400kV Susp. WT wt SI Dismantling of WT (PEDSTAL TYPE) with support structure removal of jumpers at both the ends, removal of support insulators etc. For#	1.000 EA	13691.40	13691.40
2.AU	Service 50015752	998736	ER_Dismantling 220kV Susp. WT w/o SI Dismantling of WT only PEDSTAL TYPE without support structure with removal of jumpers at both the ends etc. For#	1.000 EA	4527.65	4527.65
2.AV	Service 50015753	998736	ER_Dismantling 400kV Susp. WT w/o SI Dismantling of WT only PEDSTAL TYPE without support structure with removal of jumpers at both the ends etc. For#	1.000 EA	11202.92	11202.92
2.AW	Service 50015755	998736	ER_Erection of 220kV WT wt Insulator Erection of WT PEDSTAL TYPE with support insulators, leveling, erection of WT and connecting the Jumpers at both the ends with terminal clamps provided for#	1.000 EA	7186.55	7186.55
2.AX	Service 50015756	998736	ER_Erection of 400kV Susp. WT wt SI Erection of WT PEDSTAL TYPE with support insulators, leveling, erection of WT and connecting the Jumpers at both the ends with terminal clamps provided for#	1.000 EA	15212.14	15212.14

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.AY	Service 50015758	998736	ER_Erection of 220kV WT w/o Insulator Erection of WT only PEDSTAL TYPE without support insulators, connecting the Jumpers at both the ends with terminal clamps. For#	1.000 EA	5030.59	5030.59
2.AZ	Service 50015759	998736	ER_Erection of 400kV Susp. WT w/o SI Erection of WT only PEDSTAL TYPE without support insulators, connecting the Jumpers at both the ends with terminal clamps. For#	1.000 EA	12448.35	12448.35
2.BA	Service 50019027	998736	ER_Dismantling 400kV CVT Dismantling of 420kV CVT from support structure with removal of cabling / termination from MB and stacking the same at required place as directed#	1.000 EA	12602.09	12602.09
2.BB	Service 50019026	998736	ER_Erection of 400kV CVT Erection of 420kV CVT on provided support structure with jumper connection with suitable terminal clamp provided with connecting the required cables from MB and termination complete#	1.000 EA	15753.21	15753.21
2.BC	Service 50015760	998736	ER_Repl. 22-220kV Single Ten. String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	24458.12	24458.12
2.BD	Service 50015762	998736	ER_Repl. Twin Ten. Insulator String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	32611.22	32611.22
2.BE	Service 50015763	998519	ER_Repl. Qaudraple Ten. String Replacement of TENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	57070.53	57070.53

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.BF	Service 50015764	998736	ER_Repl. 22-220kV Single Susp. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	5187.91	5187.91
2.BG	Service 50015765	998736	ER_Repl. 22-220kV Twin Susp.Insu. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	6670.50	6670.50
2.BH	Service 50015766	998736	ER_Repl. Qaudraple Susp. String Replacement of SUSPENSION disc insulator string with removal of hardware connected, jumpers connected and its re-erection with new insulators and making the connection of all earlier jumpers etc.#	1.000 EA	10006.35	10006.35
2.BJ	Service 50015808	995461	ER_Dismantling 220kV BPI Dismantling of BPI from the support structure with removal of jumper and terminal clamp complete for#	1.000 EA	1796.04	1796.04
2.BK	Service 50015809	995461	ER_Dismantling 400kV BPI Dismantling of BPI from the support structure with removal of jumper and terminal clamp complete for#	1.000 EA	2303.75	2303.75
2.BL	Service 50015811	995461	ER_Erection of 220kV BPI Erection of BPI in stacks on provided support structure with leveling with fixing of terminal clamp with connecting the jumper for#	1.000 EA	2155.97	2155.97
2.BM	Service 50015812	995461	ER_Erection of 400kV BPI Erection of BPI in stacks on provided support structure with leveling with fixing of terminal clamp with connecting the jumper for#	1.000 EA	2763.78	2763.78
2.BN	Service 50015814	998736	Dismantling 220kV Couplg Cap. (ER/BD) Dismantling of CC from the support structure with removal of jumper and terminal clamps, removal of earthing complete for#	1.000 EA	4491.89	4491.89

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount	
2.BP	Service 50018538	998719	ER_Erection of 220kV Coupling Capacitor Erection of CC on provided support structure with connecting the terminal clamp and jumper connection with fixing of LMU unit with connection of HF cable, with connection of earthing complete for#	1.000 EA	5389.32	5389.32	
2.BQ	Service 50015816	998736	ER_Repl. Jumper Connection/Single Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	727.00	727.00	
2.BR	Service 50015817	998736	ER_Repl. Jumper Connection/Twin Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	1454.00	1454.00	
2.BS	Service 50015818	998736	ER_Repl. Jumper Connection/Quad Replacement of jumper connection with its removal with spacers from the equipment terminals with removal of connector and its re-erection with provided terminal clamps at both ends#	1.000 EA	2906.80	2906.80	
2.BT	Service 50015819	995469	ER_Repl. 22-220kV Jumper Conn./1Main Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	889.08	889.08	
2.BU	Service 50015820	996912	ER_Repl. 22-220kV Jumper Conn./2Main Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	1600.59	1600.59	
2.BV	Service 50015821	995469	ER_Repl. Jumper Connection/Quad Bus Replacement of jumper connection with spacers from the MAIN BUS from Isolators and its re-erection with given terminal clamps at both ends#	1.000 EA	3202.37	3202.37	

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.BW	Service 50015822	995469	ER_Repl. 22-220kV Jumper Conn./1Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	1067.85	1067.85
2.BX	Service 50015823	995469	ER_Repl. 22-220kV Jumper Conn./2Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	1779.36	1779.36
2.BY	Service 50015824	995469	ER_Repl. Jumper Connection/Quad Stud Bus Replacement of jumper connection ( REMOVAL & REFITTING ) with spacers from STUB BUS with its removal from Suspension insulator string hardware etc. from both ends and re-erection with provided terminal clamps at both ends#	1.000 EA	3557.52	3557.52
2.BZ	Service 50015825	995469	ER_Repl. Single Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	727.00	727.00
2.CA	Service 50015826	995469	ER_Repl. Twin Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	1454.00	1454.00
2.CB	Service 50015827	995469	ER_Repl. Quad Terminal Clamp Replacement of Terminal clamp with new one at equipment terminal with removal of jumper from both ends with crimping and refitting#	1.000 EA	2906.80	2906.80
2.CC	Service 50010134	998736	Dismantling&Erection of IPS tube Replacement of IPS tube from the equipment terminals in 400kV switchyard with removal of terminal connectors at both ends and its re-erection with provided terminal connectors#	1.000 EA	550.61	550.61

# Amathematical State Electricity Transmission Co. Ltc

# Tender for Operations and maintenance

Information

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.CD	Service 50008567	998736	Fixing 4" Al IPS Tube Fixing of IPS tube on Post Insulators ( 400kV or 33kV - tertiary ) with provided clamp as directed#	1.000 EA	306.29	306.29
2.CE	Service 50014788	998736	Fabr.&Cutting for 4" IPS Tube Fabrication of IPS Jointing Sleeves as per drawings#	1.000 EA	2223.90	2223.90
2.CF	Service 50006570	998736	Argon Welding of IPS Tube Per Joint Welding of IPS tubes joints as per site requirement with argon welding as directed to make the joint smooth#	1.000 EA	7411.80	7411.80
2.CG	Service 50018234	998736	Dismantling IPS Tube wt Str Dismantling of 4" IPS tube including supply of all labour T&P etc. complete.#	1.000 RMT	255.05	255.05
2.CH	Service 50015697	995469	ER_Crimping of Single T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	741.30	741.30
2.CJ	Service 50015696	995469	ER_Crimping of Twin T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	1482.60	1482.60
2.CK	Service 50015695	995469	ER_Crimping of Quad T Connector Crimping works ON CONDUCTOR with suitable size capacity crimping machine ( overhead ) with suitable size DIES for MAIN BUS jumpers T-clamps#	1.000 EA	2223.90	2223.90
2.CL	Service 50015691	998631	ER_Crimping of 132/220kV Jumper Cone Crimping works FOR CONDUCTOR with suitable size capacity crimping machine with suitable size DIES for JUMPER CONE at ground#	1.000 EA	593.52	593.52
2.CM	Service 50015693	995469	ER_Crimping of 400kV Jumper Cone Crimping works FOR CONDUCTOR with suitable size capacity crimping machine with suitable size DIES for JUMPER CONE at ground#	1.000 EA	1185.84	1185.84

# Tender for Operations and maintenance

Information

RFx number: 7000024010 Version: 1

Item	Item category Product no.	HSN/SA C No.	Description	Qty	Unit Rate	Amount
2.CN	Service 50015692	998736	ER_Crimping of 132/220kV Repair Sleeves Crimping works ON CONDUCTOR FOR REPAIR SLEEVES ( Overhead ) with suitable size capacity crimping machine with suitable size DIES#	1.000 EA	2965.20	2965.20
2.CP	Service 50015694	998736	ER_Crimping of 400kV Repair Sleeves Crimping works ON CONDUCTOR FOR REPAIR SLEEVES ( Overhead ) with suitable size capacity crimping machine with suitable size DIES#	1.000 EA	5929.21	5929.21

(\*Unit Rate mentioned is inclusive of all taxes)



**Information** RFx number: 7000024010 Version: 1

#### Annexure - I

(\* NR is for Invalid Condition)

Item	Product No.	HSN/SAC	GST App. in %	Item type	Conditions*
1		998736	18.00	Е	
1.AA	50015703	998736	18.00	Е	EXW,
1.AB	50015704	998736	18.00	Е	EXW,
1.AC	50000172	998736	18.00	Е	EXW,
1.AD	50000173	998736	18.00	Е	EXW,
1.AE	50015709	998736	18.00	Е	EXW,
1.AF	50015720	998736	18.00	Е	EXW,
1.AG	50015722	998736	18.00	Е	EXW,
1.AH	50015723	998736	18.00	Е	EXW,
1.AJ	50015725	998736	18.00	Е	EXW,
1.AK	50015726	998736	18.00	Е	EXW,
1.AL	50015727	998736	18.00	Е	EXW,
1.AM	50015728	998736	18.00	Е	EXW,
1.AN	50015729	998736	18.00	Е	EXW,
1.AP	50015730	998736	18.00	Е	EXW,
1.AQ	50015731	998736	18.00	Е	EXW,
1.AR	50015732	998736	18.00	Е	EXW,
1.AS	50015749	998736	18.00	Е	EXW,
1.AT	50015750	998736	18.00	Е	EXW,
1.AU	50015752	998736	18.00	Е	EXW,
1.AV	50015753	998736	18.00	Е	EXW,
1.AW	50015755	998736	18.00	Е	EXW,
1.AX	50015756	998736	18.00	Е	EXW,
1.AY	50015758	998736	18.00	Е	EXW,
1.AZ	50015759	998736	18.00	Е	EXW,
1.BA	50019027	998736	18.00	Е	EXW,
1.BB	50019026	998736	18.00	Е	EXW,
1.BC	50015760	998736	18.00	Е	EXW,
1.BD	50015762	998736	18.00	Е	EXW,
1.BE	50015763	998736	18.00	Е	EXW,
1.BF	50015764	998736	18.00	Е	EXW,
1.BG	50015765	998736	18.00	Е	EXW,
1.BH	50015766	998736	18.00	Е	EXW,
1.BJ	50015808	998736	18.00	Е	EXW,
1.BK	50015809	998736	18.00	Е	EXW,



Information

Item	Product No.	HSN/SAC	GST App. in %	Item type	Conditions*
1.BL	50015811	998736	18.00	Е	EXW,
1.BM	50015812	998736	18.00	Е	EXW,
1.BN	50015814	998736	18.00	Е	EXW,
1.BP	50018538	998736	18.00	Е	EXW,
1.BQ	50015816	998736	18.00	Е	EXW,
1.BR	50015817	998736	18.00	Е	EXW,
1.BS	50015818	998736	18.00	Е	EXW,
1.BT	50015819	998736	18.00	Е	EXW,
1.BU	50015820	998736	18.00	Е	EXW,
1.BV	50015821	998736	18.00	Е	EXW,
1.BW	50015822	998736	18.00	Е	EXW,
1.BX	50015823	998736	18.00	Е	EXW,
1.BY	50015824	998736	18.00	Е	EXW,
1.BZ	50015825	998736	18.00	Е	EXW,
1.CA	50015826	998736	18.00	Е	EXW,
1.CB	50015827	998736	18.00	Е	EXW,
1.CC	50010134	998736	18.00	Е	EXW,
1.CD	50008567	998736	18.00	Е	EXW,
1.CE	50014788	998736	18.00	Е	EXW,
1.CF	50006570	998736	18.00	Е	EXW,
1.CG	50018234	998736	18.00	Е	EXW,
1.CH	50015697	998736	18.00	Е	EXW,
1.CJ	50015696	998736	18.00	Е	EXW,
1.CK	50015695	998736	18.00	Е	EXW,
1.CL	50015691	998736	18.00	Е	EXW,
1.CM	50015693	998736	18.00	Е	EXW,
1.CN	50015692	998736	18.00	Е	EXW,
1.CP	50017771	998736	18.00	Е	EXW,
1.CQ	50017768	998736	18.00	Е	EXW,
1.CR	50017052	998736	18.00	Е	EXW,
1.CS	50009523	998736	18.00	Е	EXW,
1.CT	50007561	998736	18.00	Е	EXW,
1.CU	50017759	998736	18.00	Е	EXW,
1.CV	50005249	998736	18.00	Е	EXW,
1.CW	50004899	998736	18.00	Е	EXW,
1.CX	50004921	998736	18.00	Е	EXW,
1.CY	50015522	998736	18.00	Е	EXW,
1.CZ	50017674	998736	18.00	Е	EXW,
1.DA	50017672	998736	18.00	Е	EXW,
1.DB	50017671	998736	18.00	Е	EXW,



Information

Item	Product No.	HSN/SAC	GST App. in %	Item type	Conditions*
1.DC	50016768	998736	18.00	Е	EXW,
1.DD	50016752	998736	18.00	Е	EXW,
1.DE	50016769	998736	18.00	Е	EXW,
1.DF	50016770	998736	18.00	Е	EXW,
1.DG	50016750	998736	18.00	Е	EXW,
1.DH	50017666	998736	18.00	Е	EXW,
1.DJ	50017822	998736	18.00	Е	EXW,
1.DK	50017820	998736	18.00	Е	EXW,
1.DL	50017818	998736	18.00	Е	EXW,
1.DM	50017832	998736	18.00	Е	EXW,
1.DN	50017801	998736	18.00	Е	EXW,
1.DP	50017805	998736	18.00	Е	EXW,
1.DQ	50017807	998736	18.00	Е	EXW,
1.DR	50017813	998736	18.00	Е	EXW,
1.DS	50017826	998736	18.00	Е	EXW,
1.DT	50017814	998736	18.00	Е	EXW,
1.DU	50003606	998736	18.00	Е	EXW,
1.DV	50017809	998736	18.00	Е	EXW,
1.DW	50015694	998736	18.00	Е	EXW,
2		998736	18.00	Е	
2.AA	50015703	998736	18.00	Е	EXW,
2.AB	50015704	998736	18.00	Е	EXW,
2.AC	50000172	998736	18.00	Е	EXW,
2.AD	50000173	998736	18.00	Е	EXW,
2.AE	50015709	998736	18.00	Е	EXW,
2.AF	50015720	998736	18.00	Е	EXW,
2.AG	50015722	998736	18.00	Е	EXW,
2.AH	50015723	998736	18.00	Е	EXW,
2.AJ	50015725	998736	18.00	Е	EXW,
2.AK	50015726	998736	18.00	Е	EXW,
2.AL	50015727	998736	18.00	Е	EXW,
2.AM	50015728	998736	18.00	Е	EXW,
2.AN	50015729	998736	18.00	Е	EXW,
2.AP	50015730	998736	18.00	Е	EXW,
2.AQ	50015731	998736	18.00	Е	EXW,
2.AR	50015732	998736	18.00	Е	EXW,
2.AS	50015749	998736	18.00	Е	EXW,
2.AT	50015750	998736	18.00	Е	EXW,
2.AU	50015752	998736	18.00	Е	EXW,
2.AV	50015753	998736	18.00	Е	EXW,



Information

Item	Product No.	HSN/SAC	GST App. in %	Item type	Conditions*
2.AW	50015755	998736	18.00	Е	EXW,
2.AX	50015756	998736	18.00	Е	EXW,
2.AY	50015758	998736	18.00	Е	EXW,
2.AZ	50015759	998736	18.00	Е	EXW,
2.BA	50019027	998736	18.00	Е	EXW,
2.BB	50019026	998736	18.00	Е	EXW,
2.BC	50015760	998736	18.00	Е	EXW,
2.BD	50015762	998736	18.00	Е	EXW,
2.BE	50015763	998519	18.00	Е	EXW,
2.BF	50015764	998736	18.00	Е	EXW,
2.BG	50015765	998736	18.00	Е	EXW,
2.BH	50015766	998736	18.00	Е	EXW,
2.BJ	50015808	995461	18.00	Е	EXW,
2.BK	50015809	995461	18.00	Е	EXW,
2.BL	50015811	995461	18.00	Е	EXW,
2.BM	50015812	995461	18.00	Е	EXW,
2.BN	50015814	998736	18.00	Е	EXW,
2.BP	50018538	998719	18.00	Е	EXW,
2.BQ	50015816	998736	18.00	Е	EXW,
2.BR	50015817	998736	18.00	Е	EXW,
2.BS	50015818	998736	18.00	Е	EXW,
2.BT	50015819	995469	18.00	Е	EXW,
2.BU	50015820	996912	18.00	Е	EXW,
2.BV	50015821	995469	18.00	Е	EXW,
2.BW	50015822	995469	18.00	Е	EXW,
2.BX	50015823	995469	18.00	Е	EXW,
2.BY	50015824	995469	18.00	Е	EXW,
2.BZ	50015825	995469	18.00	Е	EXW,
2.CA	50015826	995469	18.00	Е	EXW,
2.CB	50015827	995469	18.00	Е	EXW,
2.CC	50010134	998736	18.00	Е	EXW,
2.CD	50008567	998736	18.00	Е	EXW,
2.CE	50014788	998736	18.00	Е	EXW,
2.CF	50006570	998736	18.00	Е	EXW,
2.CG	50018234	998736	18.00	Е	EXW,
2.CH	50015697	995469	18.00	Е	EXW,
2.CJ	50015696	995469	18.00	Е	EXW,
2.CK	50015695	995469	18.00	Е	EXW,
2.CL	50015691	998631	18.00	Е	EXW,
2.CM	50015693	995469	18.00	Е	EXW,



Information

RFx number: 7000024010 Version: 1

Item	Product No.	HSN/SAC	GST App. in %	Item type	Conditions*
2.CN	50015692	998736	18.00	Е	EXW,
2.CP	50015694	998736	18.00	Е	EXW,

(\* PFQ -> Packing and Forwarding Per QuantityFRQ-> Freight Per QuantityFR%-> Freight in Percentage,EXW ->Ex-Works (Basic Price),PFP-> Packing and Forwarding in Percentage,INQ-> Insurance Per Quantity,INP -> Insurance in Percentage,DISCQ-> Discount Per Quantity,DISCP->Discount in Percentage )